

5. Install the radio.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Amount
08-92-PF-90	Remove Radio and Correct Wiring At radio Connector	0.5 Hrs

**FAILURE CODE:**

68	Noisy
----	-------